

BULLETIN NO. 14/15-008

DATE: 19 Dec 14

TO: ALL ISR Affiliates

SUBJECT: 600RS - Rebalancing the Stuffing Blocks of the Crankshaft

PROBLEM

The screws securing stuffing blocks on the crankshaft can break allowing the detachment of the blocks. This situation could cause severe collateral damages into the engine

SOLUTION

Using the procedure described in this bulletin, rebalance the stuffing blocks to limit the stress on retaining screws.

See Attachment for further instructions.

[Click Here](#)

International Snowmobile Racing, Inc.