TO: ISR Oval Affiliates, Manufacturers & Specialty **Manufacturers Distributors Group**

SUBJECT: RULE BOOK CORRECTIONS

Page 70 - Outlaw 600 enclosed cockpit.

Track & Traction: Item No. 5 - The second sentence should read as follows:

The stud shank must be .175 diameter or greater at the point of juncture to the carbide tip.

The word "shank" was omitted in the rulebook.